



Recall Campaign

NHTSA # 15V-259 TC # 2015-233

Job Code 9901237

RC024 Inspection of Axle Tag for Date .2 per Axle** LCI Inspection Step 1

RC025 Inspection of Drum for Type .2 per Drum ** LCI Inspection Step 2

RC026 Replacement of Hub as required .5 per Hub

ACTION REQUIRED:

Inspect Axle Tag for manufacture date of 3/13, 3/17, 4/10, 4/13, 4/14, or 4/15

ONLY if Date on Axle Tag matches one of the dates listed, proceed to inspect for type of Drums on axle.

Compare axle manufacture date and Drum type to LCI chart to confirm if Hub must be replaced.

Replace required hub/s following LCI Trailer Axle Hub Replacement Instructions provided.

Axle DOM	Drum Type	Must Replace Hub?
3/13, 3/17	Tru Ryde	Yes
3/13, 3/17	Axle Tek	No
3/13, 3/17	LCI	No
4/10, 4/13, 4/14, 4/15	Tru Ryde	No
4/10, 4/13, 4/14, 4/15	Axle Tek	Yes
4/10, 4/13, 4/14, 4/15	LCI	No

MODELS / UNITS:

2015 Eagle Fifth Wheels

30.5BHLT F1WB 0076,0078-0082

PARTS KIT

Order parts kit from LCI according to LCI instructions provided

LCI CONTACT INFORMATION
574-537-8900 OR WARRANTY@LCI1.COM

IMPORTANT: PLEASE NOTE SPECIAL LCI INSTRUCTIONS REGARDING WHAT IS REQUIRED ON CLAIMS FOR PROCESSING